## VILLAGE OF STONINGTON, ILLINOIS IMPORTANT NOTICE

FEDERAL REGULATION 192.16 REQUIRES THAT WE INFORM OUR CUSTOMERS TO EXERCISE CAUTION REGARDING UNDERGROUND OR BURIED GAS PIPING. THIS PIPING MAY BE SUBJECT TO LEAKAGE OR CORROSION AND POTENTIALLY BE SUBJECT TO HAZARDS IF NOT MAINTAINED. REMEMBER THAT ANY PIPING DOWNSREAM OF THE GAS METER BELONGS TO THE CUSTOMER. THE CUSTOMER IS RESPONSIBLE FOR MAINTENANCE AND OPERTATION OF THIS PORTION OF THE FUEL LINE.

- **BURIED PIPING SHOULD BE:** 
  - 1. CHECKED FOR LEAKS PERIODICALLY.
  - 2. INSPECTED FOR CORROSION.
  - 3. REPAIRED IF UNSAFE CONDITION IS FOUND.
  - 4. LOCATED AND MARKED IF EXCAVATION IS PERFORMED NEAR GAS LINE.

THIS IS A NOTICE ONLY. IF YOU HAVE ANY QUESTIONS OR COMMENTS PLEASE CONTACT THE GAS DEPARTMENT.

VILLAGE OF STONINGTON, ILLINOIS 217-325-3621